

Dokumentacja fotograficzna

załącznik nr 1 do zapytania ofertowego nr DGN.2216.1.21.2018 z dnia 07.09.2018 r.


I. Trybuna I



1




2



3



4



5



6



7



8



9



10



11



12



13



14



15



16



17

II. Trybuna II



18



19



20



21



22



23



24



25



26



27



28

III. Trybuna III



29



30



31



32



33




34



35



36



37



38



39

IV. Trybuna IV



40



41



42




43



44



45



46



47



48



49



50



51


v. **Membrana**







VI. Brak jednej nakrętki




















VII. Brak zabezpieczeń



VIII. Cybanty bez śrub





IX. Luźno leżące nakrętki



X. Rozkręcone kontry





